

An Roinn Iompair, Turasóireachta agus Spóirt Department of Transport, Tourism and Sport

# Traffic Signs Manual

Current Review and Updates

Bernard Sweeney May 8<sup>th</sup> 2019 Lyrath Estate Hotel, Kilkenny.

### Contents



## Current Update of the TSM Advice Notes Website







## Current Update of the TSM

**Current Update** 





INTRODUCTION AND SIGN LOCATION

CHAPTER 1 April 2019



**Current Update** 




### **Cardinal Reference Symbols**



DIRECTIONAL INFORMATION SIGNS

CHAPTER 2



### Terminal Destinations Updated Use of IATA codes

2.2.19 Where an airport name is displayed with the Airport symbol the IATA Airport code may be used instead of the name. e.g. for Ireland West Airport – NOC.

**Current Update** 





VARIABLE MESSAGE SIGNS

CHAPTER 3 April 2019

### Figure 3.4 - Revised




3.3.9 This sign or combination of signs may be provided on one or both sides of the road at the entry point of the section of road defined in the relevant bye-law. At the end of the defined section of road, permanent signs shall be provided indicating the relevant speed limit beyond the Periodic Speed Limit (see Chapter 5). These can normally be mounted on the rear of the Periodic Speed Limit signs.











## more on this later...



**Current Update** 



Surfacing joints not to be placed where longitudinal lines are required (para 7.3.7). Centreline to be omitted on roads less than 5.0m wide, to be provided on roads greater than 6.0m wide and is optional on roads between 5.0m and 6.0m in width (paras 7.3.12 and 7.3.14).

Centreline marking to be 100mm wide on roads of 80km / or less and to be 150mm



CHAPTER 7 April 2019

An Koinn Iompair, Turasóireachta agus Spói Department of Transport.

ROAD MARKINGS

Reference to constraint imposed by necessity to use bi-inigual information has been removed (para 7.5.27).

Use of warning line along downhill side of climbing lane permitted (para 7.3.38). Changes to stud spacings: continuous centreline to have 6m stud spacing; warning centreline line to have 12m spacing generally.

Clarification on the use of green study at junctions.


Requirements outlined for the marking of passing bays (recently introduced in TII Standards); markings for nearside passing bays (no longer in TII Standards) removed from the Chapter. Associated changes to various figures.

# •

Your PC ran into a problem that it couldn't handle, and now it needs to restart We're just collecting some error info, and then we'll restart for you.

If you'd like to know more, you can search online later for this error: DPC\_WATCHDOG\_VIOLATION

Presentation Basics				
toc much text for one single slide - consider using abbreviations or something				
	Cancel	ОК	CA_LIN JERRY	



**Current Update** 








## Advice Notes



 Rural Speed Limit
 Slow Zones
 Drive on Left
 Emergency Diversions
 Advice Notes



- 80 km/h speed limit remains
- Visual target removed
- Single Lane Local Tertiary
- Selected Secondaries
- Not for other messages



### Rural Speed Limit Slow Zones Drive on Left Emergency Diversions Advice Notes





### Rural Speed Limit Slow Zones Drive on Left Emergency Diversions Advice Notes





### Rural Speed Limit Slow Zones Drive on Left Emergency Diversions Advi

**Advice Notes** 








## Website

trafficsigns.ie





An Roinn Iompair, Turasóireachta agus Spóirt Department of Transport, Tourism and Sport

# Go raibh maith agat

Bernard Sweeney – Kildare County Council DTTAS Support Office

bernard.sweeney@dttassupportoffice.ie 045-988 951 087-278 9617

